

Church of St Dunstan, Wenden Lofts

Description

The original building of the C12 was completely rebuilt in 1845-6 and the original C12 south door was incorporated. The interior of the church has been entirely dismantled and the building is now a shell.

Risk

An overgrown and ruinous shell. Consolidation work to fabric required.

Suggested immediate actions

- Vegetation to be removed
- Vulnerable areas of structure to be propped and supported
- Openings to be secured as necessary.



Summary

• • •

Parish Wenden Lofts

Designation Grade II

List Entry ID 1273778

Priority A

Condition Very bad

Date Registered 1986

Ownership Private

For sale No

Last site visit

29/4/2015


National Grid

reference TL 46387

38731

Contact 01799 510510

Map



LB at Risk
Church of Dunstan, Wenden Lofts



UDC © Crown copyright and database rights
2014 Ordnance Survey 0100018688