

# Tilty Mill, Tilty

## Description

Watermill. Early C18, heightened in C19, and most of the machinery dates from the later period. Red brick with tiled roof, half-hipped with a gablet at one end and a weatherboarded lucam for sack-hoisting at the other. Two storeys and attics; 3 windows. One gabled dormer with boarded loading door below. Cambered casements and central doorcase.

## Risk

Vacant early C18 watermill with mechanism still intact but suffering from structural problems and lack of maintenance. Recommendations made by the District Council and Historic England for enabling development and conversion to residential use refused by Inspector.

## Suggested immediate actions

- Vegetation to be removed
- Vulnerable areas of structure to be propped and supported
- Openings to be secured



## Summary

• • •

**Parish** Tilty

**Designation** Grade II\*

**List Entry ID** 1112221

**Priority** A

**Condition** Poor

**Date Registered** 1986

**Ownership** Private

**For sale** No

**Last site visit**

29/4/2015


**National Grid**

**reference** TL 59944

26734

**Contact** 01799 510510

# Map



LB at Risk  
Tilty Mill



UDC © Crown copyright and database rights  
2014 Ordnance Survey 0100018688