

Roothers Farm, Debden Green, Henham Road, Debden

Description

C17 timber-framed and plastered building with a C18 addition at the rear. Two storeys. The upper storey is jettied at the south-west end of the front. The windows are partly double-hung sashes and partly casements. Roof tiled, with one external chimney stack.

Risk

House is vacant and in a dilapidated condition with the openings unprotected, leaving the building vulnerable to further deterioration.

Suggested immediate actions

- Openings to be secured allowing for adequate ventilation

Summary

•••

Parish Debden

Designation II

List Entry ID 1305838

Priority A

Condition Poor

Date Registered

03/11/2015

Ownership Private

For sale No

Last site visit

National Grid


reference TL57860

31810

Contact 01799 510531



Map



LB at Risk
Roothers, Debden Green, Henham Road, Debden



UDC © Crown copyright and database rights 2014 Ordnance Survey 0100018688